

FITNESS CERTIFICATE OF SCHOOL BUILDING

(To be filled by the inspecting officer)

- 1 Name of the officer : Adarsh P.R
- 2 Name of the School : Vimala Public School Vettimatton
- 3 Location with name of Education Sub District : Vettimatton, Thochipuzha
DGF:(31.10x8.40+12.70x4.30)x3.5
2) FF
(31.10x8.40+12.70x4.30)x3.5
3)SF:
(31.10x8.40+12.70x4.30)x3.5 4)Cellar
(35.27x10.50+6.52x9.21)x3.5
- 4 Classification of building as specified in col.of the application for fitness certificate :
- 5 Period for which the certificate is issued : 2021-22
- 6 Nature of defect if any :
- a) Foundation and basement : Nil
- b) Superstructure : Nil
- c) Doors and windows : Nil
- d) Wood work wrought and put up : Nil
- e) Roof : Nil
- f) Flooring : Nil
- g) Miscellaneous : Nil
- 7 Any major defects noticed which will render the building unsafe in any manner : Nil
- 8 whether maintenance works have been done properly : Yes
- 9 whether the structure is sound or not for conducting classes : Sound Under Normal Weather condition (1 Hall with Trussed Sheet Roofing, Fitness issued as per Order No. PAN/15733/2019-13(DP) Dtd.13/05/2020

Note: 1)The stability of the structure should be examined also with reference to the location altitude,intensity of wind exposure to flood.

2)Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the school was inspected by me on **21.06.2021** and found to fit/unfit for conduct classes for the period of **1 year (31.05.2022)** for the reasons stated above.

Place: Pannimatton

Signature : 

Designation:



Assistant Engineer
L.B.G.D. Section Office
Vettimatton Gramapanchayath
Thochipuzha, Thucki Dist., Kerala